

KNKT Notification No. KNKT.22.12.17.04

Name, Organization and contact information of person/organization submitting notification:		Komite Nasional Keselamatan Transportasi (National Transportation Safety Committee) Ministry of Transportation Building 3 rd Floor Jl. Medan Merdeka Timur No. 5 Jakarta - INDONESIA Telephone: + 62 21 3517606 Facsimile: + 62 21 3517606 24-hour Call Contact +62 81212655155 Website: www.knkt.dephub.go.id/knkt Email: knkt@kemenhub.go.id
a) for accidents the identifying abbreviation ACCID, for serious incidents SINCID, for incidents INCID;	SINCID (Serious Incident)	
b) manufacturer, model, nationality and registration marks, and serial number of the aircraft;	Manufacturer : Robinson Helicopter Company Model : R66 Nationality : Indonesia Registration : PK-VPJ Serial Number : 0897	
c) name of owner, operator and hirer, if any, of the aircraft;	Owner : PT. Volta Pasifik Aviasi Operator : PT. Volta Pasifik Aviasi	
d) qualification of the pilot-in-command, and nationality of the crew and passengers;	Pilot in Command qualification : CPL/H Flight crew nationality : Indonesia Passengers nationality : Russia	
e) date and time (local time or UTC) of the occurrence;	Local Time Date : 1 December 2022 Time : 1300 LT	UTC Date : 1 December 2022 Time : 0500 UTC
f) last point of departure and point of intended landing of the aircraft;	Last point of departure : Flybali Heliport, Bali, Indonesia Point of intended landing: Flybali Heliport, Bali, Indonesia	
g) position of the aircraft with reference to some easily defined geographical point and latitude and longitude;	The occurrence location was about 75 meters from main helipad at Flybali Heliport, Bali.	
h) number of crew and passengers; aboard, killed and seriously injured; others, killed and seriously injured;	Persons on board were 1 pilot and 3 passengers. No one injured in this occurrence.	
i) description of the occurrence and the extent of damage to the aircraft so far as is known;	During approach for landing, the helicopter entered nose down attitude. Just before touching the ground, the pilot recovered to level the helicopter and landed on the grass about 30 meters from the intended landing point. No one was injured and the landing gear cross tube was found yielding beyond serviceable limit.	
j) an indication to what extent the investigation will be conducted or is proposed to be delegated by the State of Occurrence;	The KNKT classified this occurrence as Serious Incident and will conduct an investigation in accordance with the provisions of Annex 13 to the Convention on International Civil Aviation.	
k) physical characteristics of the occurrence area, as well as an indication of access difficulties or special requirements to reach the site;	The occurrence location was at Flybali Heliport in Bali, Indonesia. The location is accessible with a permit from the heliport operator.	

l) identification of the originating authority and means to contact the investigator-in-charge and the accident investigation authority of the State of Occurrence at any time;	The KNKT Indonesia Telephone : + 62 21 3517606 Facsimile : + 62 21 3517606 24-hour Call Contact : +62 81212655155 Email : aviation.knkt@kemenhub.go.id		
m) presence and description of dangerous goods on board the aircraft.	No		
Operation Type (If information is available)	Commercial Aviation	Non Scheduled	Passenger
Level of damage to aircraft (If information is available)	Minor		
The State of Occurrence shall forward notification of an accident or serious incident with a minimum of delay and by the most suitable and quickest means available to a) the State of Registry; b) the State of the Operator; c) the State of Design; d) the State of Manufacture; and e) the International Civil Aviation Organization, when the aircraft involved is of a maximum mass of over 2 250 kg.			