

KNKT Notification**No. KNKT.23.03.04.04**

Name, Organization and contact information of person/organization submitting notification:



**Komite Nasional Keselamatan Transportasi
(National Transportation Safety Committee)**

Ministry of Transportation Building 3rd Floor
Jl. Medan Merdeka Timur No. 5 Jakarta - INDONESIA
Telephone: + 62 21 3517606
Facsimile: + 62 21 3517606
24-hour Call Contact +62 81212655155
Website: www.knkt.go.id
Email: aviation.knkt@kemenhub.go.id

a) for accidents the identifying abbreviation ACCID, for serious incidents SINCID, for incidents INCID;	SINCID (Serious Incident)	
b) manufacturer, model, nationality and registration marks, and serial number of the aircraft;	Manufacturer : Boeing, USA Model : B737-800 Nationality : Indonesia Registration : PK-GMC Serial Number : 30155	
c) name of owner, operator and hirer, if any, of the aircraft;	Owner : Falcon Aerospace France 2 SARL Operator : PT Garuda Indonesia	
d) qualification of the pilot-in-command, and nationality of the crew and passengers;	Pilot in Command qualification : ATPL Flight crew nationality : Indonesia Passengers nationality : Indonesia	
e) date and time (local time or UTC) of the occurrence;	Local Time Date : 30 March 2023 Time : 1753 LT	UTC Date : 30 March 2023 Time : 1053 UTC
f) last point of departure and point of intended landing of the aircraft;	Last point of departure : Suvarnabhumi Airport (VTBS), Bangkok, Thailand Point of intended landing: Soekarno-Hatta International Airport (WIII), Jakarta, Indonesia	
g) position of the aircraft with reference to some easily defined geographical point and latitude and longitude;	After the occurrence, the aircraft was parked at PT Garuda Maintenance Facility (GMF) AeroAsia, Soekarno-Hatta International Airport (WIII), Jakarta, Indonesia.	
h) number of crew and passengers; aboard, killed and seriously injured; others, killed and seriously injured;	Person on board were 2 pilots, 6 attendants, and 77 passengers. No one was injured in this occurrence.	
i) description of the occurrence and the extent of damage to the aircraft so far as is known;	During landing at Soekarno-Hatta International Airport, Jakarta (WIII), the aircraft experienced high vertical acceleration. During the walkaround check, it was found that the tail section of the aircraft had been damaged, indicating a tail-strike landing.	
j) an indication to what extent the investigation will be conducted or is proposed to be delegated by the State of Occurrence;	The KNKT classified this occurrence as Serious Incident and will conduct an investigation in accordance with the provisions of Annex 13 to the Convention on International Civil Aviation.	
k) physical characteristics of the occurrence area, as well as an indication of access difficulties or special requirements to reach the site;	The occurrence location was at Soekarno-Hatta International Airport (WIII), Jakarta, Indonesia. The airport can be accessed by regular flight.	
l) identification of the originating authority and means to contact the investigator-in-charge and the accident investigation authority of the State of Occurrence at any time;	The KNKT Indonesia Telephone : + 62 21 3517606 Facsimile : + 62 21 3517606 24-hour Call Contact : + 62 81212655155 Email : aviation.knkt@kemenhub.go.id	

m) presence and description of dangerous goods on board the aircraft.	None
Operation Type (If information is available)	Commercial scheduled passenger flight
Level of damage to aircraft (If information is available)	Minor
The State of Occurrence shall forward a notification of an accident or serious incident with a minimum of delay and by the most suitable and quickest means available to: a) the State of Registry; b) the State of the Operator; c) the State of Design; d) the State of Manufacture; and e) the International Civil Aviation Organization, when the aircraft involved is of a maximum mass of over 2,250 kg.	